


## Notations of Dimensioning



## Units of Dimensioning

As far as possible all dimensions should be given in millimeters omitting the abbreviation mm.

If another unit is used, only the dimension figures should be written. But a footnote such as 'All the dimensions are in centimeters' is inserted in a prominent place near the title box.

e.g. 15.50

0.75 (Zero must precede the decimal point.)

15.50 ± .75 (Zero is omitted.)