


PREPARATORY STEPS FOR PLOTTING

- There are three methods of plotting.
 - Type Plot at the command prompt.
 - Click Plot from the Standard toolbar.
 - Click File >> Plot from the pull down menu bar.



DIPLOMA ENGINEERING IN AIRCRAFT MAINTENANCE
DWM 1203: TECHNICAL DRAWING AND CAD

FOR TRAINING PURPOSE ONLY
JPP/DWM1203/P14/REV00

Preview from Notesale.co.uk
Page 2 of 10

DETERMINE PART OF DRAWING TO PLOT

- When plotting a drawing, you must specify the area of the drawing to plot.
- Options under Plot Area :-
 - **Layout or Limits**
 - When plotting a layout, this option plots everything within the margins of the specified paper size, with the origin calculated from 0,0 in the layout.
 - When plotting on the Model tab, it plots the entire drawing area defined by the drawing limits.
 - If the current viewport does not display a plan view, this option has the same effect as the Extents option.
 - **Display**
 - Plots the view in the current viewport in the Model tab or the current paper space view in a layout tab.

DIPLOMA ENGINEERING IN AIRCRAFT MAINTENANCE
DWM 1203: TECHNICAL DRAWING AND CAD

FOR TRAINING PURPOSE ONLY
JPP/DWM1203/P14/REV00