


2. 611-PV-315B



2 . 611-PV-315B

As Found:

1. Valve plug and cage badly scratch and pitted.
2. Seat ring had scratch and pitted.

As Left

1. Re-used existing valve trims. Only valve plug replaced with old plug .
2. Apply lapping on valve plug and seat.
3. Do cleaning with sand paper on the inner cage.

Preview from Notesale.co.uk
Page 5 of 10