

temperature ranges are considered. It can severely affect the stability of a system at high temperature if not considered properly. Improvements in construction techniques have resulted in significantly lower levels of I_{CO} , to the point where its effect can often be ignored.




Figure 5.0 Majority and minority carrier flow of a pnp transistor

Preview from Notesale.co.uk
Page 3 of 3