

Types of steam in Basic Mechanical Engineering, Saturated steam

There are three types of the steam for saturated steam that is also known as dry saturated steam.. the dryness fraction of the saturated steam is always one and that is denoted by small x . the white steam is also called as the white steam and at last superheated steam. saturated steam is heated further at constant pressure its temperature rises beyond its saturation temperature. Steam in this state is known as superheated steam.. superheated steam is completely gaseous phase that means there is no any any water molecules and so that the dryness fraction of the super heated steam is always equal to 1

Preview from Notesale.co.uk
Page 1 of 1