

WIRE ROPE INSPECTION AND STORAGE

- Never use damaged slings. Inspect slings regularly to ensure their safety. Check wire rope slings for kinking, wear, abrasion, broken wires, worn or cracked fittings, loose seizing's and splices, crushing, flattening, and rust or corrosion. Pay special attention to the areas around thimbles and other fittings.



- Slings should be marked with an identification number and their safe working load (SWL).

